

ENVIRONMENTAL MONITORING REPORT

August 2022



ADDRESS

112 Long Point Rd West,
Warkworth, Singleton
NSW 2330

CONTENTS

1.	Site Details	3
2.	Air Quality Monitoring	3
3.	Water Monitoring	3
I.	HRSTS Discharge Volume and Quality	
II.	Discharge Quality	



1. SITE DETAILS

LICENSE HOLDER

Verdant Earth Technologies

EPL NUMBER


11262 ([link](#))



2. AIR QUALITY MONITORING

Given that the plant was not operational during the reporting period, no air quality monitoring was undertaken.

3. WATER MONITORING



I. HRSTS Discharge Volume and Quality

No water was discharged under the HRSTS during the reporting period.

II. Discharge Quality

Date Sampled: See table below
Date Obtained: 16/08/2022
Date Published: 31/08/2022
Frequency: Daily during any discharge

Date Sampled	EPA ID No. 2		
	Oil & Grease	pH	TSS
	mg/L	pH units	mg/L
05/08/2022	<5	7.88	<5