



# ENVIRONMENTAL MONITORING REPORT

April 2022



## ADDRESS

112 Long Point Rd West,  
Warkworth, Singleton  
NSW 2330

# CONTENTS

|    |                        |                                    |
|----|------------------------|------------------------------------|
| 1. | Site Details           | 3                                  |
| 2. | Air Quality Monitoring | 3                                  |
| 3. | Water Monitoring       | 3                                  |
|    | I.                     | HRSTS Discharge Volume and Quality |
|    | II.                    | Discharge Quality                  |



# 1. SITE DETAILS

## LICENSE HOLDER

Verdant Earth Technologies

## EPL NUMBER

11262 ([link](#))



## 2. AIR QUALITY MONITORING

Given that the plant was not operational during the reporting period, no air quality monitoring was undertaken.

# 3. WATER MONITORING

## I. HRSTS Discharge Volume and Quality

No water was discharged under the HRSTS during the reporting period.

## II. Discharge Quality

Date Sampled: See table below  
Date Obtained: 20/04/22<sup>a</sup>, 6/05/2022<sup>b</sup>  
Date Published: 12/05/2022  
Frequency: Daily during any discharge

| Date Sampled            | EPA ID No. 2 |          |      |
|-------------------------|--------------|----------|------|
|                         | Oil & Grease | pH       | TSS  |
|                         | Mg/L         | pH units | Mg/L |
| 08/04/2022 <sup>a</sup> | <5           | 7.78     | <5   |
| 28/04/2022 <sup>b</sup> | <5           | 7.77     | <5   |