

ENVIRONMENTAL MONITORING REPORT

May 2022



ADDRESS

112 Long Point Rd West,
Warkworth, Singleton
NSW 2330

CONTENTS

| | | |
|----|------------------------|------------------------------------|
| 1. | Site Details | 3 |
| 2. | Air Quality Monitoring | 3 |
| 3. | Water Monitoring | 3 |
| | I. | HRSTS Discharge Volume and Quality |
| | II. | Discharge Quality |

1. SITE DETAILS

LICENSE HOLDER

Verdant Earth Technologies

EPL NUMBER

11262 ([link](#))



2. AIR QUALITY MONITORING

Given that the plant was not operational during the reporting period, no air quality monitoring was undertaken.

3. WATER MONITORING

I. HRSTS Discharge Volume and Quality

No water was discharged under the HRSTS during the reporting period.

II. Discharge Quality

Date Sampled: See table below

Date Obtained: 17/05/22^a, 23/05/2022^b, 03/06/2022^c, 14/06/2022^d

Date Published: 14/06/2022

Frequency: Daily during any discharge

| Date Sampled | EPA ID No. 2 | | |
|-------------------------|----------------------|----------------|-------------|
| | Oil & Grease mg/L | pH pH units | TSS mg/L |
| 05/05/2022 ^a | <5 | 7.76 | <5 |
| 13/05/2022 ^b | <5 | 7.80 | 6 |
| 23/05/2022 ^c | <5 | 7.82 | 5 |
| 24/05/2022 ^c | <5 | 8.20 | <5 |
| 31/05/2022 ^d | <5 | 8.21 | 6 |